

# łańcuch rozrządu SC0 0409 A-142 8.5441.413



Nr katalogowy: 8.5441.413

Dział: Łańcuchy rozrządu

Ilość ogniw: 142

Oznaczenie producenta: SCA 0409 DHA

Typ produktu: Łańcuch

Cena: 212.42 zł

Stara cena: 274.89 zł

Dostępność: Dostępny na zamówienie

**Opis szczegółowy:** Wszystkie łańcuszki rozrządu japońskich producentów motocykli pochodzą z firm DID oraz Borg Warner. Kupując u nas łańcuszek, otrzymujecie Państwo towar będący tej samej jakości, co fabrycznie montowany. Stałe kontrole jakościowe surowców i wykonania gwarantują produkt na poziomie najnowocześniejszej techniki.

**Lista powiązań tego produktu z innymi modelami:**

Marka	Model	Rocznik	Kod
SUZUKI	VL (C) 1500 LC Intruder	2005	AL2111
SUZUKI	VL 1500 LC Intruder	1998	AL1211
SUZUKI	VL 1500 LC Intruder	1999	AL1211
SUZUKI	VL 1500 LC Intruder	2000	AL1211
SUZUKI	VL 1500 LC Intruder	2001	AL2111
SUZUKI	VL 1500 LC Intruder	2002	AL2111
SUZUKI	VL 1500 LC Intruder	2003	AL2111
SUZUKI	VL 1500 LC Intruder	2004	AL2111
SUZUKI	VS 1400 GLF Intruder	1987	VX51L
SUZUKI	VS 1400 GLF Intruder	1988	VX51L
SUZUKI	VS 1400 GLP Intruder	1989	VX51LD
SUZUKI	VS 1400 GLP Intruder	1990	VX51LD
SUZUKI	VS 1400 GLP Intruder	1991	VX51LD
SUZUKI	VS 1400 GLP Intruder	1992	VX51LD
SUZUKI	VS 1400 GLP Intruder	1993	VX51LD
SUZUKI	VS 1400 GLP Intruder	1994	VX51L
SUZUKI	VS 1400 GLP Intruder	1995	VX51L
SUZUKI	VS 1400 GLP Intruder	1996	VX51L
SUZUKI	VS 1400 GLP Intruder	1997	VX51L
SUZUKI	VS 1400 GLP Intruder	1998	VX51L
SUZUKI	VS 1400 GLP Intruder	1999	VX51L
SUZUKI	VS 1400 GLP Intruder	2000	VX51L
SUZUKI	VS 1400 GLP Intruder	2001	VX51L
SUZUKI	VS 1400 GLP Intruder	2002	VX51L
SUZUKI	VS 1400 GLP Intruder	2003	VX51L